# General Environmental Incident Summary

Incident: 3359 Date/Time Notice: 6/22/2014 0900 DEM Incident No:

Responsible Party: ONEOK Rockies Midstream

Date Incident: 6/20/2014 Time Incident: 1830 Duration: 1 minutes

County: Williams Twp: 153 Rng: 102 Sec: 10 Qtr: SE SW

Lat: 48.08491 Long: -103.78910 Method: Navigation quality GPS

Location Description: Judson Compressor Station

4614Hwy 1804WillistonND58801

Submitted By: Kim Rudningen Affiliation: Environmental Specialist-ONEOK

Address: 2700 Lincoln Ave SE

City: Sidney State: MT Zip: 59271

Received By:

Contact Person: Kim Rudningen

2700 Lincoln Ave SE Sidney, MT 59271

Distance Nearest Occupied Building: 0.5 Miles Release Contained: Yes

Type of Incident: Tank Overflow

Description of Released Contaminant: natural gas condensates

Volume Spilled: 10.00 gallons Ag Related: No

EPA Extremely Hazardous Substance: No Reported to NRC: No

Cause of Incident:

The condensate tank burped over when filling and caused a loss of 10 gallons into the containment area and onto adjacent soil. Due to wind, a small amount landed outside of the containment.

#### Risk Evaluation:

No immediate risk to health occurred due to this release.

# of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

#### Potential Environmental Impacts:

This spill was immediately contained to the facility site. There are no other impacts to water or offsite soils.

### Action Taken or Planned:

The soil will be excavated and removed to a landfill. The spill was contained to the facility site area only. No other emergency steps were required.

Wastes Disposal Location: Permitted Landfill

Agencies Involved:

Monday, July 21, 2014 Page 1 of 2

## **Updates**

Date: 6/22/2014 Status: Reviewed; No Followup Required Staff: Roberts, Kris

## **Updated Volume:**

#### Notes:

Estimated 10-gallon release of natural gas condensates from a tank fill remained on the location and has been cleaned up. No followup necessary for this incident.

Monday, July 21, 2014 Page 2 of 2